



Inspector Name: Sample Report

Date: 7/9/08

**Vehicle Information**

Make:	PONTIAC	Model:	GTO	Year:	1969
Color:	Red	Plate:	XXX-XXX	Mileage:	70212

**Owner Information**

Name:	Joe Sample	Phone:	555-555-1111
Email:	<a href="mailto:joesample@empireautostorage.com">joesample@empireautostorage.com</a>		
Address:	123 Example Rd, Example, FL, 55555		

**Service Details**

Car Care Service:	Active Gold	Storage Date:	06/01/2007
Other Services:	_____		

**Inspection Details**

**Visual Exterior:**

Item	Change	Details
Paint	<input type="checkbox"/>	As Previous Month
Chrome	<input type="checkbox"/>	As Previous Month
Accessories	<input type="checkbox"/>	N/A
Fluid Leaks	<input checked="" type="checkbox"/>	Small transmission fluid leak seen, minor, no more than a few small spots.

**Visual Interior:**

Item	Change	Details
Dash	<input type="checkbox"/>	As Previous Month
Console	<input type="checkbox"/>	As Previous Month
Front Seats Area	<input type="checkbox"/>	As Previous Month
Back Seats Area	<input type="checkbox"/>	As Previous Month
Headliner	<input type="checkbox"/>	As Previous Month
Engine Bay	<input type="checkbox"/>	As Previous Month
Trunk Space	<input type="checkbox"/>	As Previous Month

**Fluids:**

Item	Level	Changed	Details (look, feel, added, advise)
Oil	F		_____
Transmission	F		Leak not effecting level at this time, leak should be checked but not urgent
Power Steering	N/A		_____
Washer Fluids	1/2		_____
Fuel	3/4	X	Down less than 1/8 <sup>th</sup> tank from exercise
Radiator/Coolant	F		_____



Other	N/A
-------	-----

**Running Report:**

Engine Start:	<input checked="" type="checkbox"/>	Vehicle to Running Temp:	<input checked="" type="checkbox"/>	Miles Driven:	<input checked="" type="checkbox"/>
---------------	-------------------------------------	--------------------------	-------------------------------------	---------------	-------------------------------------

**Running Notes (start, engine sound, handling, gears, other):**

Car started on 7/1/08 and 7/9/08. Started right up with no issue using normal

procedures for this car. Engine was run 15 minutes on 7/1/08 to operating temp.

with no issues.

On 7/9/08 car was brought to starting temp (12 minutes) and then driven just on

30 minutes on local roads, covering approx 18 miles. Engine was smooth

throughout. Gears shifted smoothly. Brakes were solid and smooth.

Previously noted drift to the left suggests need for tire alignment or check in the

future but remains minor and did not effect the ride in any significant way.

Weather was clear through out ride, outside temp was 85 degrees.

**Additional Notes and Attached Photos:**

No notes

Attached images: front, rear, left side, right side, engine bay, trunk, interior front,

interior back, transmission leak image (inc size marker).

Inspector Signature:	Sample Report	Date:	07/09/2008
----------------------	---------------	-------	------------